




U.S. Distribution Center
8801-B Smiths Creek Rd, Wales, MI 48027
Tel 810-367-7125 Fax 810-367-7130
Toll-Free 800-835-5992
www.ditting.com



Serving the Whole-Bean
Coffee Market Since 1968

Ditting® USA Warranty Details

Effective October 1, 2010, Ditting® USA, Inc. has extended the limited warranty on all new coffee grinders to the original buyer, as follows:

- For **new** retail grinders (to include the KF/KR804, KR805, KR1203, and KR1403 models) purchased for the **United States**, the warranty includes three years on all electric components.
- For **new** light-industrial grinders (to include the KFA1403 and KF1800 models) purchased for the **United States**, the warranty includes one year on all electric components.
- For **new** on-demand espresso grinders (640 series) purchased for the **United States**, the warranty includes one year on electric and electronic components.
- For **reconditioned** grinders purchased for the **United States**, the warranty includes 6 months on all electric components.
- For **used** grinders purchased for the **United States**, the warranty includes 3 months on all electric components.

>> For grinders purchased before October 1, 2010, new grinders purchased through Ditting USA, Inc. included a 1 year limited warranty on all electric parts.

Warranty on parts includes the motor and all other factory electric parts. Not covered under warranty: damage due to misuse or abuse, labor and shipping.

The use of any non-Ditting parts anywhere in the grinder, to include switches and grinding discs, will immediately void the warranty.

If service is needed, **Ditting® USA** should be contacted for troubleshooting or recommendation of a service company PRIOR to any labor or service being performed. Most of the time, the problem (though it might seem like a matter of life and death) could be simply power-related or a circuit breaker that has tripped for safety. **Ditting®** would like to avoid having customers face unnecessary costs. Our 40+ years of experience has shown that we can fix 99% of our grinder-related problems quickly and easily over the phone in minutes.

If the grinder is under warranty and a part needs replacement, the part will be billed (including shipping charges) and shipped to you by the requested shipping method. When you return the old part along with the model and serial number of the machine from which the part was removed, and if it is deemed defective, you will receive credit for the defective part and your cost will be for shipping only.

Ditting® USA has a list of service companies across the U.S. who service our grinders. These are independent companies and are not associated with **Ditting® USA**, and we would like to hear your experiences with them in order to concentrate only on those companies who service your machines properly, efficiently and professionally.

This warranty is put in simple words to avoid misunderstanding and/or abuse. If you have any suggestions on how we can take better care of your investment, please let us know.

Call us toll-free at 800-835-5992 for free technical assistance, service tips, and complete schematics from knowledgeable service technicians. We are here to support our customers and service centers with any questions you may have. Do not hesitate to call us.